



Umfanekiso unokuba ngumelo. I-Jonga iinkcukacha zeenkukacha zemveliso.

813252CKI-02LF

Inombolo yendawo: **813252CKI-02LF**
 Ingcaciso yeMveliso: IC MULTIPLIER VCXO PLL 32-VFQFPN
 RoHS Imeko: Ukukhokela mahala / RoHS Ukuthobela
 Maxwebhu: 813252CKI-02LF.pdf

Umkhqizi / Umshicileli: IDT (Integrated Device Technology)
 Umkhumbi: Hong Kong
 Indlela yokuthunyelwa: DHL/Fedex/TNT/UPS/EMS

NGENISA UPHANDO >

Iinkcukacha zeMveliso

Inombolo yendawo	813252CKI-02LF	Umenzi	IDT (Integrated Device Technology)
Inkcazo	IC MULTIPLIER VCXO PLL 32-VFQFPN	Isimo soBume beNkokeli / Isimo seRoHS	Ukukhokela mahala / RoHS Ukuthobela
Ishiti yedatha	813252CKI-02LF.pdf		
Ukunikezela ngeeVotsi	3.135 V ~ 3.465 V	Uhlobo	Frequency Translator, Jitter Attenuator, Multiplexer, Voltage Controlled Crystal Oscillator (VCXO)
Iphakheji yeCandelo leNkonzo	32-VFQFPN (5x5)	Uchungechunge	FemtoClock®
Ukulinganiswa - Ukufaka: Isiphumo	3:2	Packaging	Tray
Iphakheji / Iimeko	32-VFQFN Exposed Pad	PLL	Yes
Isiphumo	LVPECL	Amanye amagama	800-2670 ICS813252CKI-02LF ICS813252CKI-02LF-ND ICS813252CKI02LF
Ukushisa okusebenzayo	-40°C ~ 85°C	Inani lesekethe	1
Uhlobo lokuPhakamisa	Surface Mount	Inqanaba lokuSondeza Ubuninzi (MSL)	3 (168 Hours)
Isimo soBume beNkokeli / Isimo seRoHS	Lead free / RoHS Compliant	Input	HCSSL, LVDS, LVHSTL, LVPECL, SSTL
Ukuphindaphinda - uMax	312.5MHz	Uhlu loLuntu / uManinzi	No/Yes
Ukwahlula - Inqaku: Umphumo	Yes/Yes	Isiqendu seNombolo yeSiseko	ICS813252-02

Iimveliso ezihambelanayo

<p>8132/24 100 Abavelisi: 3M Inkcazo: CBL RIBN 24COND 0.156 GRAY 100' Ukukhuphela: 8132/24 100.pdf</p> <p><input type="button" value="RFQ"/></p>	<p>8132/22 100 Abavelisi: 3M Inkcazo: CBL RIBN 22COND 0.156 GRAY 100' Ukukhuphela: 8132/22 100.pdf</p> <p><input type="button" value="RFQ"/></p>
<p>81320 Abavelisi: Makeblock Inkcazo: TT GEARED MOTOR DC 6V/200RPM Ukukhuphela: 81320.pdf</p> <p><input type="button" value="RFQ"/></p>	<p>8132760000 Abavelisi: Weidmüller Inkcazo: SURGE PROTECTION Ukukhuphela: 8132760000.pdf</p> <p><input type="button" value="RFQ"/></p>
<p>8132FO 0601000 Abavelisi: Belden Inkcazo: CBL 2PR 28AWG SHLD</p> <p><input type="button" value="RFQ"/></p>	<p>813253BGLF Abavelisi: IDT (Integrated Device Technology) Inkcazo: IC ATTENUATOR/XLATOR 24TSSOP Ukukhuphela: 813253BGLF.pdf</p> <p><input type="button" value="RFQ"/></p>
<p>8132/18 Abavelisi: 3M Inkcazo: CBL RIBN 18COND 0.156 GRAY 100' Ukukhuphela: 8132/18.pdf</p> <p><input type="button" value="RFQ"/></p>	<p>8132/17 100 Abavelisi: 3M Inkcazo: CBL RIBN 17COND 0.156 GRAY 100' Ukukhuphela: 8132/17 100.pdf</p> <p><input type="button" value="RFQ"/></p>
<p>8132FO 060500 Abavelisi: Belden Inkcazo: CBL 2PR 28AWG SHLD</p> <p><input type="button" value="RFQ"/></p>	<p>8132/20 Abavelisi: 3M Inkcazo: CBL RIBN 20COND 0.156 GRAY 100' Ukukhuphela: 8132/20.pdf</p> <p><input type="button" value="RFQ"/></p>
<p>813253BGLFT Abavelisi: IDT (Integrated Device Technology) Inkcazo: IC ATTENUATOR/XLATOR 24TSSOP</p> <p><input type="button" value="RFQ"/></p>	<p>813252CKI-02LFT Abavelisi: IDT (Integrated Device Technology) Inkcazo: IC MULTIPLIER VCXO PLL 32-VFQFPN Ukukhuphela: 813252CKI-02LFT.pdf</p> <p><input type="button" value="RFQ"/></p>

Iimpawu ezinxulumene noko

IIDT (Integrated Device Technology) 813252CKI-02LF	Umhambisi we813252CKI-02LF	Umthengisi we813252CKI-02LF
Ixabiso le813252CKI-02LF	Imifanekiso ye813252CKI-02LF	Umfanekiso we813252CKI-02LF
Idatha ye-813252CKI-02LF PDF	I-813252CKI-02LF ikhuphele iphepha	Idatha ye-813252CKI-02LF
Isitokhwe se813252CKI-02LF	Thenga i813252CKI-02LF	Thenga iIDT (Integrated Device Technology) 813252CKI-02LF
IIDT (Integrated Device Technology) 813252CKI-02LF	Umthengisi weIDT (Integrated Device Technology)	Umhambisi weIDT (Integrated Device Technology)
IIDT (Integrated Device Technology) 813252CKI-02LF	IIDT 813252CKI-02LF	IIDT (Integrated Device Technology) 813252CKI-02LF
IIDT, Integrated Device Technology Inc 813252CKI-02LF	IIntegrated Device Technology (IDT) 813252CKI-02LF	